

FIG. 3B




FIG. 3E




FIG. 3C




FIG. 3F




FIG. 3D




FIG. 3H




FIG. 3G




FIG. 3E




FIG. 4




FIG. 5A





FIG. 5B







FIG. 5D






FIG. 6A




FIG. 6B




FIG. 6C




FIG. 6D






FIG. 7B









FIG. 8B

FIG. 8C








FIG. 9A






FIG. 10A




FIG. 10B




FIG. 11A




FIG. 12A

1200




FIG. 12B




FIG. 13




FIG. 14A




FIG. 14B





FIG. 14C

100, 400, 800, 900, 1000, 1100, 1200




FIG. 15A

1000




FIG. 15B




FIG. 15C




FIG. 15D








FIG. 15E

1519



1151






FIG. 17A

1700




FIG. 17B

1702




FIG. 17C

1704




FIG. 17D




FIG. 18A




FIG. 18B




FIG. 19A




























FIG. 19B












FIG. 23C




FIG. 25C




FIG. 24J

FIG. 24J




FIG. 25A




FIG. 25B

2400

2452

2454

FIG. 24C

106mH
or
108mH

106H
or
108H

106mS
or
108mS

106S
or
108S

106S
or
108S
or
106H
or
108H






FIG. 24C

FIG. 24D

FIG. 24E

2456

2458

2460

106H
or
108H

106H
or
106H
or
106S
or
106S
OR

108S
or
108S
or
108H
or
108H

106V
or
106V
or
108V
or
108V






FIG. 24F

FIG. 24G

FIG. 24H




FIG. 25D




FIG. 25E




FIG. 25F




FIG. 25G




FIG. 25H




FIG. 25I

2600

106(m,a)V
OR
108(m,a)V

106(m,m)V
OR
108(m,m)V

106(a,a)V
OR
108(a,a)V

106(a,m)V
OR
108(a,m)V

FIG. 26A

2600

2602

2619

2612

2602RM

106V OR 108V

421 OR
423

1120 OR 1111

2230

2614

2602R(M-1)

106V OR 108V

2602RL

106V OR 108V

2602Ra

106V OR 108V

2320

2614

2217
OR
2418

2605

2250

FIG. 26B

2700




FIG. 27A




FIG. 27B


2800 →

$106(m,a)s'$
OR
 $108(m,a)s'$

$106(n,m)s'$
OR
 $108(n,m)s'$

$106(a,a)s'$
OR
 $108(a,a)s'$

$106(a,n)s'$
OR
 $108(a,n)s'$



2250

FIG. 28


2900 →

$106(m,a)s$
OR
 $108(m,a)s$

$106(n,m)s$
OR
 $108(n,m)s$

$106(a,a)s$
OR
 $108(a,a)s$

$106(a,n)s$
OR
 $108(a,n)s$



2250

FIG. 29

3/8




FIGURE 31




FIGURE 32:

3300




FIGURE 33: